CORROSION RESISTANCE OF FISH TAGGING PINS



2



UNITED STATES DEPARTMENT OF THE INTERIOR FISH AND WILDLIFE SERVICE



EXPLANATORY NOTE

The series embodies results of investigations, usually of restricted scope, intended to aid or direct management or utilization practices and as guides for administrative or legislative action. It is issued in limited quantities for official use of Federal, State or cooperating agencies and in processed form for economy and to avoid delay in publication. United States Department of the Interior, Fred A. Seaton, Secretary Fish and Wildlife Service, Arnie J. Suomela, Commissioner

CORROSION RESISTANCE OF FISH TAGGING PINS

by

Albert C. Jensen Fishery Research Biologist Bureau of Commercial Fisheries



United States Fish and Wildlife Service Special Scientific Report--Fisheries No. 262

> Washington, D. C. December 1958

The Library of Congress has cataloged this publication as follows:

Jensen, Albert C

Corrosion resistance of fish tagging pins. Washington, . U. S. Dept. of the Interior, Fish and Wildlife Service, 1958.

6~p,~illus,~27~cm,~(U,~8,~Fish~and~Wildlife~Service,~Special scientific report ; fisheries no. <math display="inline">262)

Bibliography: p. 4.

1. Fish tagging. I. Title. (Series)

SH11.A335 no. 262 639.2

59-60033

Library of Congress

The Fish and Wildlife Service series, Special Scientific Report--Fisheries, is cataloged as follows:

> U. S. Fish and Wildlife Service. Special scientific report: fisheries. no. 1-(Washington, 1949-

> > no. ilius., maps, diagrs. 27 cm.

Supersedes in part the Service's Special scientific report.

1. Fisheries-Research.

59-60217

Library of Congress

SH11.A335

(2)

639.2072

ABSTRACT

Aquarium-held haddock were tagged with nickel and Type 304 stainless steel pins to compare the corrosion resistance of the two metals. The stainless steel pins proved to be superior.

CONTENT

Conditions of the experiment
Tanks
Fish
Method of tagging
Control pins
Fish survival
Results
Nickel pins
On tagged fish
Controls
Stainless steel pins 3
On tagged fish
Controls
Discussion and conclusions
Effects of tags on the fish 4
Literature cited
Appendix
Table A 5
Table B 6

Page

•

Wire or pins made of various metals, including silver, platinum, copper, and nickel, have been used extensively to fasten tags to fish. For some years nickel pins were used with Petersen discs to mark haddock (<u>Melanogrammus aeglefinus L.</u>) in the Gulf of Maine (Rounsefell 1941) and on Georges Bank. When recovered many of them were corroded, suggesting that many tags may have been lost from the fish. To avoid this loss, stainless steel pins were considered as a possible substitute.

An experiment with tagged haddock was conducted in the Fish and Wildlife Service aquarium at Woods Hole to compare the corrosion resistance of Type 304 stainless steel pins with that of the nickel pins used in the past. The metallic composition and dimensions of the two types of pins are shown in table 1.

CONDITIONS OF THE EXPERIMENT

Tanks

Six indoor aquaria each holding about 300 gallons were used in the experiment.

Table 1. --Composition and dimensions of tagging pins $\frac{1}{2}$

Stainless Steel		Nickel		
Chromium	18.7%	Nickel	98.5%	
Nickel	10.7	Cobalt	0.5	
Molybdenum	0.22	Silicon	0.3	
Carbon	0.08	Manganese	0.2	
Titanium*	0.1	Copper	0.2	
Niobium*	0.1	Iron	0.1	
Iron	$\frac{70.1}{100.0}$		99.8	
Length (in.)	1,53	Length (in.)	1.81	
Diameter (in.)	. 035	Diameter (in.)	,032	

*Spectrographic analysis

1/ Analyzed by National Bureau of Standards

Flowing sea water at the rate of four changes per day was supplied to the tanks from Great Harbor, on which the laboratory is located. The water temperature in the tanks was recorded with a Bristol recording thermometer. The average salinity of the water in Great Harbor is 32 parts per thousand, and because of the frequency of change the salinity of the aquarium water was presumably the same.

Fish

The haddock used in the experiment were captured by an otter trawl on Georges Bank during <u>Albatross III</u> cruise 59, April 6-12, 1955. A total of 168 fish were transported to Woods Hole on board the vessel in wooden tanks supplied with running sea water.

Haddock are delicate and difficult to maintain in aquaria. Four weeks were therefore allowed for initial mortality and to acclimate the fish before the experiment began. Forty-three fish survived and 36 of the strongest, ranging in size from 30 centimeters to 60 centimeters, were selected for use.

Method of Tagging

The fish were tagged with Petersen discs on May 9 using the technique described by Rounsefell (1941) in which the pin is threaded through the center of one disc and then pushed through the operculum from the inside. The second disc is then threaded on the projecting point of the pin. The surplus part of the pin is cut off and the remainder twisted into a loop and bent over with long-nosed pliers. To calm the fish while being tagged, they were placed in a tank containing 12 gallons of sea water to which one-half pound of ethyl carbamate (Urethane) had been added. After about one minute in the anesthetizing bath the fish began to float belly up, made only feeble swimming movements and were generally relaxed enough to permit tagging. On 18 fish the tags were fastened with stainless steel pins and on the other 18 fish the

tags were fastened with nickel pins. Three fish tagged with stainless steel pins and three fish tagged with nickel pins were placed in each tank.

Control Pins

In addition to pins attached to the fish, two groups of control pins were set up to distinguish the effects of the raw harbor water, the aquarium water and the body fluids of the fish. A group of 10 stainless steel pins and 10 nickel pins were put in the aquarium water with the fish and a similar group was placed in the harbor. Half of these pins were bent as in tagging and half were left straight to see if bending affected the resistance to corrosion.

Fish Survival

There was some mortality throughout the experiment, but 20 fish survived for eight weeks. All these died during the ninth week, probably from lethal water temperatures. Previous studies at Woods Hole have shown that haddock do not survive well at water temperatures higher than 65° F. The temperature in the tanks was 53° F. on May 9 and reached 65° F. on June 19, six weeks later. The temperature continued

Table 2. -- Abstract of the experimental log

Dat	e	Water Temperature (degrees Fahrenheit)	Number of fish alive
May	9	53	36
	16	54	32
	23	57	27
	30	59	26
June	6	60	25
	13	62	25
	20	67	22
	27	69	22
July	4	70	20
	12	70	All dead

rising until it reached 70° F. on July 1. The last fish succumbed on July 12. These data are shown in table 2.

Although 36 fish had been tagged, only 34 tags were recovered from fish during the course of the experiment. The tags which had fallen off two fish were later recovered from the bottom of the tank. When a fish died its tags and pin were removed intact and washed in fresh water. The tag number, the date and the condition of the tagging wound were noted. At the end of the experiment the control pins were removed from the tanks and the harbor and washed in fresh water. All pins were examined under a binocular microscope for evidence of corrosion.

RESULTS

Nickel Pins

On Tagged Fish

All the nickel pins were corroded except one pin that was on a fish which died the day after tagging. Most of the nickel pins were corroded where they passed through the operculum and were in contact with tissue. The degree of corrosion varied

> from minor (staining and shallow etching on the surface metal) to extensive (deep etching and weakening of the metal). Two pins were partially worn through from abrasion by the tag discs, one was abraded by the inner disc, the other by the outer disc.

> Three pins appeared sound on the surface but broke when bent, revealing a hollow corroded interior covered by a thin skin of apparently unaffected metal. This phenomenon has also been noted by Calhoun, Fry, and Hughes (1951) and Forrester and Ketchen (1955). In one case the nickel pin weakened and broke, allowing the pin head and inner disc to fall off the fish. The rest of the pin and the outer disc remained attached to the fish. This probably explains the loss of both tags by two fish on which nickel pins had been used. Table 3 summarizes the condition of nickel pins on tagged fish.



Attaching a Petersen disc tag to the operculum of a haddock.

Controls

All of the nickel pins in the aquarium control lot were corroded. In the bent pins the degree of failure ranged from pitting and surface corrosion to hollowing. All of the straight pins were hollowed, and broke when tested with pliers.

The control pins in the harbor showed varied resistance to corrosion. Two bent pins bore minor surface corrosion at the bend, the other three were unaffected. Two of the straight pins showed minor surface corrosion and one was unaffected. The remaining two were lost during the experiment.

Stainless Steel Pins

On Tagged Fish

The stainless steel pins were almost completely free from corrosion. Three pins showed rust spots and one pin was partially worn through by abrasion from the outer disc. These results agree well with those of Forrester and Ketchen (1955) who used pins of Type 316 stainless steel in a field tagging study. Type 316 differs from the Type 304 used in this experiment mainly in having 15 times as much molybdenum (Anon. 1947).

Controls

None of the control stainless steel pins were affected by immersion in the aquarium or in the harbor.

Table 3. --Summary of the average condition of the nickel pins used to tag fish

Time on Fish Days	Condition	
1 - 21	Minor corrosion	
22 - 42	Moderate surface corrosion	
43 - 61	Moderate to extensive corrosion	
62 - 64	Extensive corrosion; hollowed pins	

Most of the structural damage to the pins occurred where the pin contacted fish tissue. Body fluids of the fish may have been primarily responsible for the corrosion of the nickel pins on fish. Additional factors (Calhoun, Fry and Hughes 1951) which may have entered into the process which caused the pin damage are the galvanic effect produced by dissimilar metals (i.e., stainless steel, nickel and the iron pipes and drain screens) immersed in the aquarium tanks and/or the concentration-cell effect produced by a metal immersed in a mixture of electrolytes (i.e., fish excretory products and sea water). Electrolysis from either cause, coupled with actual chemical corrosion, would accelerate destruction of the pins. This could explain why the nickel control pins in the tanks were more corroded than the nickel control pins in the harbor which corroded slightly or not at all.

The artificiality of the aquarium tanks as a fish habitat should be considered before any strict conclusions are drawn concerning the usefulness of the pins which were tested in this study. However, since the nickel pins did corrode in the aquarium and to some extent in the harbor, it is reasonable to assume they would corrode in the open sea over a period of months instead of weeks. This conclusion is supported by the number of nickel pins which have corroded in the field tagging of haddock. Similarly, since the stainless steel pins did not corrode in the aquarium or in the harbor they probably would not corrode in field use. Based on the results

of these studies we have decided to stop using nickel pins for tagging haddock.

Since the Type 304 stainless steel pins we tested are resistant to corrosion by the metabolic products of the haddock and also resistant to corrosion by raw sea water, we are using them exclusively in field tagging of several marine species. The pins were used in an extensive haddock tagging program conducted in 1956 and 1957. When sufficient returns are available, the relative corrosion resistance of the stainless steel and the nickel pins in actual field use will be compared.

EFFECTS OF TAGS ON THE FISH

Although the study was conducted to compare the corrosion resistance of the two types of tagging pins, observations also were made on the effects of the tags and the tagging technique upon the opercula on which the tags were fastened.

Damage to the operculum occurred in almost all the haddock which survived more than two weeks after tagging, varying from a mild inflammation to severe ulceration. In an extreme case, extensive necrosis occurred which resulted in loss of the tag. This tag was recovered intact from the bottom of the tank. When examined, the fish was found to have a raw hole about 3/4 inches in diameter where the tag had been applied.

On seven fish the inner disc was partially or completely grown over with tissue, but no fish had only the outer disc grown over. On one fish both inner and outer discs were grown over. The concealment of Petersen discs by overgrowth of tissue may be a factor contributing to rapidly diminishing returns from field tagging (Rounsefall 1941).

Black granular tissue which surrounded the pin for a radius of about 1/4 inch was seen on seven fish, five of which had been tagged with nickel pins.

Opercular ulcerations occurred on eight fish which were tagged with nickel pins and on twelve which were tagged with stainless steel pins. The small increase in ulceration associated with the stainless steel pins may have been a result of the stiffness of these pins. They are slightly more resistant to bending than are the nickel pins. The tagger's unfamiliarity with the new pin material caused him to exert more pressure when twisting the pins and this resulted in tight tags. Pressure from the tag discs probably caused a sore to develop beneath the discs which ultimately led to a deep ulceration. This hypothesis about the causes of the tagging wounds is supported by the effects of three tags which had been loosely fastened. One fish had been tagged with a stainless steel pin and developed only a slight sore under the discs. The other two fish had been tagged with nickel pins; one developed no sore under the discs, the second developed only minor sores.

LITERATURE CITED

ANONYMOUS

1947. Fabrication of U.S.S. stainless and heat resisting steels. U.S. Steel Corp., Carnegie-Illinois Steel Corp., Pittsburgh-Chicago, 136 pp.

CALHOUN, A. J., D. H. FRY, JR., AND E. P. HUGHES

1951. Plastic deterioration and metal corrosion in Petersen disc tags. Calif. Fish and Game 37(3): 301-314.

FORRESTER, C. R., AND K. S. KETCHEN

1955. The resistance o salt water corrosion of various types of me metal wire used in the tagging of flatfish. Jour. Fish. Res. Bd. Can. 12(1): 134-142.

ROUNSEFELL, GEORGE A.

1941. Field experiments in selecting the most efficient tag for use in haddock studies. Trans. Amer. Fish. Soc. 71:228-235.

APPENDIX

Table A. --Condition of pins and opercula following tagging

Nicl	kel F	Pins
------	--------------	------

9857Lost in tank.sides.around pin.2257Extensive surface corrosion at operculum. Abraded by inner disc.Minor ulcerationBlack granular tis. around pin.8257Moderate surface corrosion at operculum. Abraded by outer disc.Moderate ulcerationBlack granular tis. around pin.4357Extensive surface corrosion at operculum.Moderate ulcerationBlack granular tis. around pin.4357Extensive surface corrosion at operculum.Severe ulcerationBlack granular tis. around pin.5958Moderate surface corrosion at operculum.Severe ulcerationTight tag, dropped operculum.5958Moderate surface corrosion at operculum.Moderate ulcerationBlack granular tis. around pin.3158Moderate surface corrosion at operculum.GoodLoose tag. at operculum.7659Minor surface corrosion at operculum.GoodLoose tag. at operculum.2761Moderate surface corrosion at operculum.DecomposedDead in tank sever days.2963Hollowed at operculum.DecomposedDead in tank sever days.	Tag No.	Days on Fish $\frac{1}{2}$ /	Pin Condition	O perculum Condition	Remarks
2110Minor surface corrosion at operculum.Good5121Minor surface corrosion at operculum.Good5121Minor surface corrosion at operculum.Good5342Moderate surface corrosion 	60	1	No corrosion	Good	
5121Minor surface corrosion at operculum.Good1542Moderate surface corrosion at operculum.Ulcerated, both sides.3342Moderate surface corrosion at operculum.Good3753Hollowed at operculum.Minor sore, both sides.Black granular tisk around pin.9657Lost in tank.Extensive surface corro- sion at operculum. Abraded by inner disc.Minor ulceration disc grown over.Black granular tisk around pin.8257Moderate surface corro- sion at operculum. Abraded by outer disc.Misor ulceration disc grown over.Black granular tisk around pin.4357Extensive surface corro- sion at operculum.Moderate ulceration disc grown over.Black granular tisk around pin.5958Moderate surface corro- sion at operculum.Severe ulceration ulceration internally.Black granular tisk around pin.7659Moderate surface corro- sion at operculum.GoodLoose tag.7659Minor surface corro- sion at operculum.GoodLoose tag.7659Minor surface corro- sion at operculum.GoodLoose tag.7761Moderate surface corro- sion at operculum.GoodLoose tag.782963Hollowed at operculum.Decomposed around pin.Decad in tank sever days.	41	8		Good	
5121Minor surface corrosion at operculum.Good operculum.1542Moderate surface corrosion at operculum.Ulcerated, both sides.3342Moderate surface corrosion at operculum.Good3753Hollowed at operculum.Minor sore, both sides.Black granular tist around pin.9857Lost in tank.Extensive surface corro- sion at operculum. Abraded by inner disc.Minor ulceration externally. Inner disc grown over.Black granular tist around pin.8257Extensive surface corro- sion at operculum. Abraded by outer disc.Moderate ulceration disc grown over.Black granular tist around pin.4357Extensive surface corro- sion at operculum.Severe ulceration externally. Inner disc grown over.Black granular tist around pin.5958Moderate surface corro- sion at operculum.Severe ulceration externally. Moderate ulceration internally.Black granular tist around pin.3158Moderate surface corro- sion at operculum.GoodLoose tag.7659Minor surface corroo- sion at operculum.GoodLoose tag.7659Minor surface corroo- sion at operculum.GoodLoose tag.7761Moderate surface corroo- sion at operculum.GoodLoose tag.785963Hollowed at operculum.Decomposed days.Dead in tank sever days.	21	10		Good	
at operculum, at operculum.sides. Good3342Moderate surface corrosion at operculum.Good3753Hollowed at operculum.Minor sore, both sides.Black granular tist around pin.9857Lost in tank.Image: Side corrosion disc grown over.Black granular tist around pin.8257Extensive surface corro- sion at operculum. Abraded by inner disc.Minor ulceration disc grown over.Black granular tist around pin.8257Moderate surface corro- sion at operculum. Abraded by outer disc.disc grown over.Black granular tist around pin.4357Extensive surface corro- sion at operculum. by outer disc.Severe ulceration externally. Inner around pin.Black granular tist around pin.5958Moderate surface corro- sion at operculum. externally. Moderate ulceration internally.Tight tag, dropped operculum.7659Moderate surface corro- sion at operculum. Pin both sides.GoodLose tag.7659Minor surface corro- sion at operculum. Pin both sides.GoodLose tag.7659Minor surface corro- sion at operculum.GoodLose tag.7761Moderate surface corro- sion at operculum. Pitted under head.Decomposed Dead in tank sever days.Black granular tist around pin.2963Hollowed at operculum.Decomposed CordDead in tank sever days.	51	21	Minor surface corrosion at	Good	
33 42 Moderate surface corrosion at operculum. Good 37 53 Hollowed at operculum. Minor sore, both sides. Black granular tist around pin. 98 57 Lost in tank. Black granular tist around pin. 22 57 Extensive surface corro- sion at operculum. Abraded by inner disc. Minor ulceration externally. Inner sion at operculum. Abraded by outer disc. Black granular tist around pin. 82 57 Moderate surface corro- sion at operculum. Abraded by outer disc. externally. Inner disc grown over. Black granular tist around pin. 43 57 Extensive surface corro- sion at operculum. Severe ulceration disc grown over. Black granular tist around pin. 59 58 Moderate surface corro- sion at operculum. Severe ulceration externally. Moderate ulceration internally. Black granular tist around pin. 31 58 Moderate surface corro- sion at operculum. Pin pitted near head on shank. Good Loose tag. 76 59 Minor surface corro- sion at operculum. Pitted both sides. Loose tag. Joose tag. 27 61 Moderate surface corro- sion at operculum. Pitted under head. Decomposed Dead in tank sever days. 80 63 Hollowed and	15	42		•	
3753Holowed at operculum.Minor sore, both sides.Black granular tist around pin.9857Lost in tank	33	42	Moderate surface corrosion		
2257Extensive surface corro- sion at operculum. Abraded by inner disc.Minor ulceration externally. Inner disc grown over.Black granular tist around pin.8257Moderate surface corro- sion at operculum. Abraded by outer disc.Moderate ulceration disc grown over.Black granular tist around pin.4357Extensive surface corro- sion at operculum.Moderate ulceration externally. Inner disc grown over.Black granular tist around pin.4357Extensive surface corro- sion at operculum.Severe ulceration externally. Inner around pin.Black granular tist around pin.5958Moderate surface corro- sion at operculum.Severe ulceration externally. Moderate ulceration internally.Black granular tist around pin.3158Moderate surface corro- sion at operculum.Moderate ulceration externally. Moderate ulceration internally.Black granular tist around pin.7659Minor surface corro- sion at operculum.GoodLoose tag.2761Moderate surface corro- sion at operculum.Minor ulceration, both sides.Loose tag.2963Hollowed at operculum.DecomposedDead in tank sever days.8063Hollowed and broken. HeadGoodPart of tag broken	37	53	•		Black granular tissue around pin.
sion at operculum. Abraded by inner disc.externally. Inner disc grown over.around pin.8257Moderate surface corro- sion at operculum. Abraded 	98	57	Lost in tank.		
8257Moderate surface corro- sion at operculum. Abraded by outer disc.Moderate ulceration externally. Inner disc grown over.Black granular tist around pin.4357Extensive surface corro- sion at operculum.Severe ulceration externally. Inner disc grown over.Black granular tist around pin.5958Moderate surface corro- sion at operculum.Severe ulceration externally. Inner disc grown over.Tight tag, dropped operculum.3158Moderate surface corro- sion at operculum.Moderate ulceration ulceration internally.Black granular tist around pin.3158Moderate surface corro- sion at operculum.Moderate ulceration both sides.Black granular tist around pin.7659Minor surface corro- sion at operculum.GoodLoose tag.2761Moderate surface corro- sion at operculum.Minor ulceration, both sides.Loose tag.2963Hollowed at operculum.DecomposedDead in tank sever days.8063Hollowed and broken. HeadGoodPart of tag broken	22	57	sion at operculum. Abraded	externally. Inner	Black granular tissue around pin.
4357Extensive surface corrosion at operculum.Severe ulcerationBlack granular tist around pin.5958Moderate surface corrosion at operculum.Severe ulcerationTight tag, dropped operculum.3158Moderate surface corrosion at operculum.Moderate ulcerationBlack granular tist around pin.3158Moderate surface corrosion at operculum.Moderate ulcerationBlack granular tist around pin.3158Moderate surface corrosion at operculum.Moderate ulcerationBlack granular tist around pin.7659Minor surface corrosion at operculum.GoodLoose tag.2761Moderate surface corrosion at operculum.Minor ulceration, both sides.Loose tag.2963Hollowed at operculum.DecomposedDead in tank sever days.8063Hollowed and broken. HeadGoodPart of tag broken	82	57	Moderate surface corro- sion at operculum. Abraded	Moderate ulceration externally. Inner	Black granular tissue around pin.
5958Moderate surface corro- sion at operculum.Severe ulceration externally. Moderate ulceration internally.Tight tag, dropped operculum.3158Moderate surface corro- sion at operculum. Pin pitted near head on shank.Moderate ulceration both sides.Black granular tist around pin.7659Minor surface corrosion at operculum.GoodLoose tag.2761Moderate surface corro- 	43	57	Extensive surface corro-	Severe ulceration externally. Inner	Black granular tissue around pin.
3158Moderate surface corro- sion at operculum. Pin pitted near head on shank.Moderate ulceration both sides.Black granular tist 	59	58		Severe ulceration externally. Moderate	Tight tag, dropped of operculum.
7659Minor surface corrosion at operculum.GoodLoose tag.2761Moderate surface corro- sion at operculum. Pitted under head.Minor ulceration, 	31	58	sion at operculum. Pin	Moderate ulce r ation	Black granular tissue around pin.
27 61 Moderate surface corro- sion at operculum. Pitted under head. Minor ulceration, both sides. Loose tag. 29 63 Hollowed at operculum. Decomposed Dead in tank sever days. 80 63 Hollowed and broken. Head Good Part of tag broken	76	59	Minor surface corrosion	Good	Loose tag.
2963Hollowed at operculum.DecomposedDead in tank sever days.8063Hollowed and broken. HeadGoodPart of tag broken	27	61	Moderate surface corro- sion at operculum. P itted		Loose tag.
80 63 Hollowed and broken. Head Good Part of tag broken	29	63		Decomposed	Dead in tank several days.
and inner disc missing in off.	80	63	and inner disc missing in	Good	Part of tag broken off.
32 63 Lost in tank.	32	63			

 $\frac{1}{2}$ Days on fish refers to elapsed time between the day the fish was tagged and the day it died.

APPENDIX

Table B. -- Condition of pins and opercula following tagging

Stainless Steel Pins

Tag No.	Days on Fish <u>1</u> /	Pin Condition	O perculum Condition	Remarks
19	4	No corrosion	Good	
71	7	No corrosion	Good	
94	7	No corrosion	Good	
57	8	No corrosion	Good	
77	8	No corrosion	Good	
70	14	No corrosion	Moderate ulceration both sides of operculum.	
24	22	No corrosion	Ulcerated, both sides.	
56	42	Rust spot at twist.	Ulcerated, both sides.	Tight tag.
45	53	No corrosion.	Ulcerated, both sides. Inner and outer discs grown over.	
89	57	No corrosion	Minor ulceration externally.	
03	51	110 0011 031011	Inner disc grown over.	
84	58	No corrosion	Moderate ulceration exter- nally. Inner disc partially grown over.	
65	58	Abraded by outer disc. Rust spot at twist.	Severe ulceration exter- nally. Inner disc grown over.	Black granular tissue around pin.
42	58	No corrosion	Good	
91	58	No corrosion	Severe ulceration exter- nally. Inner disc grown over.	Tight tag.
64	61	No corrosion	Severe ulceration, both sides.	Tight tag.
39	61	No corrosion except black spot near pin head.	Severe ulceration, both sides.	
03	63	Abraded by outer disc. Rust spot at twist.	Severe ulceration, both sides.	Black granular tissue around pin.
46	64	No corrosion	Minor ulceration externally.	Loose tag.

 $\frac{1}{2}$ Days on fish refers to elapsed time between the day the fish was tagged and the day it died.

